



Figure 5 Debris marked awaiting collection.




Figure 6 Left-hand lane, in the area of the first tyre mark.